# NH2000 FIRMWARE UPDATE

The undervoltage protection response has been updated in the NH2000 Inverter's firmware starting in version V1.08. The changes reduce nuisance tripping while still ensuring component safety and protection.



## NEW FIRMWARE UDPATE: V1.08

- **The DC undervoltage protection has a 30 second delay, provided the input voltage stays above 10.0 VDC.**
- **AC Undervoltage protection has a 2 second delay.**

## FIRMWARE UPDATE PROCEDURE

**STEP 1:** Download the TBB Connection mobile app.

**STEP 2:** Power up the inverter and turn the mobile device's bluetooth on.

**STEP 3:** Open the app and select the inverter from the device list. Note: the device name may start with **"BLE"** or **"DTU"**.

**STEP 4:** Press the settings **(GEAR)** icon in the top right corner.

**STEP 5:** Press **"Device Information"** and **"Inverter"**.

**STEP 6:** Under **"Firmware Version"**, if there is a new version available, you will see it displayed in orange. Press the orange text and begin the update.

**STEP 7:** Keep the device powered on throughout the update and reboot the inverter once it's complete.

## MOBILE APP

TBB Connection

App Store

Google Play



fsi-solutions.com | info@fsi-sales.com | 574-262-3688 | 2616 Glenview Dr, Elkhart IN 46514 | Future Solutions™ is a Division of FSi™